

25 Coyote Trail Cascade, ID 83611 P: 208-382-5726 C: 208-634-6896

Annexation Parcel 122.407 Acres

A parcel of land located in a portion of, Section 31, T.14 N., R. 4 E., B.M., Valley County, Idaho, being more particularly described as follows:

BEGINNING at a found brass cap monument marking the south 1/4 corner of said Section 31 (CP&F Inst. No. 353930 corner records of said Valley County); Thence a bearing of N 89°29′46″ W, a distance of 601.17 feet on the south boundary of said Section 31 to a found aluminum cap right-of-way monument at station 638+32.99, 75′ Rt. on the northeasterly right-of-way boundary of State Highway 55 as shown on I.T.D. Highway Plans as Project No. BR-3270(158) and further shown on Record of Survey book 11, page 151, records of said Valley County;

Thence on said northeasterly right-of-way boundary of State Highway 55, 256.77 feet on the arc of a curve to the right said curve having a radius of 9,925.00 feet, a delta angle of 1°28′56″ and a long chord which bears N 44°19′49″ W, a distance of 256.76 feet to a found aluminum cap right-of-way monument at station 640+91.72, 75′ Rt. said highway plans;

Thence a bearing of N 43°35′21″ W, a distance of 408.83 feet on said northeasterly right-of-way boundary to a found aluminum cap right-of-way monument at station 845+00.54, 75′ Rt. said I.T.D. Project No. BR-3270(158);

Thence on said northeasterly right-of-way boundary a bearing of N 47°20′39″ E, a distance of 7.01 feet to a found I.T.D. brass cap right-of-way monument at station 645+00, 60′ Rt. as shown on I.T.D. Highway Plans as Project No. F-3271(1);

Thence on said northeasterly right-of-way boundary a bearing of N 43°35′49″ W, a distance of 47.76 feet to a set 5/8 inch rebar on the Ordinary High Water Line (O.H.W.L.) on the left bank of the North Fork of the Payette River;

Thence the following bearings and distances on said O.H.W.L.:

Thence a bearing of N 84°46′04″ E, a distance of 43.13 feet to a set 5/8 inch rebar; Thence a bearing of S 70°17′27″ E, a distance of 25.36 feet to a set 5/8 inch rebar; Thence a bearing of S 70°17′27″ E, a distance of 21.33 feet to a set 5/8 inch rebar; Thence a bearing of N 56°40′02″ E, a distance of 57.11 feet to a set 5/8 inch rebar; Thence a bearing of N 87°27′04″ E, a distance of 44.70 feet to a set 5/8 inch rebar; Thence a bearing of S 77°09′45″ E, a distance of 81.42 feet to a set 5/8 inch rebar; Thence a bearing of N 86°24′49″ E, a distance of 36.18 feet to a set 5/8 inch rebar; Thence a bearing of N 76°38′03″ E, a distance of 26.12 feet to a set 5/8 inch rebar; Thence a bearing of N 49°23′22″ E, a distance of 22.75 feet to a set 5/8 inch rebar; Thence a bearing of N 18°08′45″ E, a distance of 22.61 feet to a set 5/8 inch rebar; Thence a bearing of N 74°41′52″ W, a distance of 38.32 feet to a set 5/8 inch rebar; Thence a bearing of N 86°36′46″ W, a distance of 48.32 feet to a set 5/8 inch rebar; Thence a bearing of S 79°59′26″ W, a distance of 31.12 feet to a set 5/8 inch rebar; Thence a bearing of S 79°59′26″ W, a distance of 31.12 feet to a set 5/8 inch rebar;





Annexation Parcel 122.407 Acres continued

Thence a bearing of N 58°56′18″ W, a distance of 13.64 feet to a set 5/8 inch rebar; Thence a bearing of N 21°29′59″ E, a distance of 56.42 feet to a set 5/8 inch rebar; Thence a bearing of N 64°19'31" E, a distance of 14.91 feet to a set 5/8 inch rebar; Thence a bearing of N 44°18′58″ E, a distance of 113.29 feet to a set 5/8 inch rebar; Thence a bearing of N 56°55′24″ W, a distance of 47.10 feet to a set 5/8 inch rebar; Thence a bearing of S 57°15′54" W, a distance of 23.34 feet to a set 5/8 inch rebar; Thence a bearing of \$57°12'04" W, a distance of 51.01 feet to a set 5/8 inch rebar; Thence a bearing of S 31°32′26″ W, a distance of 19.69 feet to a set 5/8 inch rebar; Thence a bearing of S 13°45′51" W, a distance of 50.90 feet to a set 5/8 inch rebar; Thence a bearing of S 34°49′29″ W, a distance of 45.66 feet to a set 5/8 inch rebar; Thence a bearing of S 51°42′00″ W, a distance of 15.26 feet to a set 5/8 inch rebar; Thence a bearing of N 87°47′55″ W, a distance of 78.23 feet to a set 5/8 inch rebar; Thence a bearing of N 36°25′43″ E, a distance of 76.92 feet to a set 5/8 inch rebar; Thence a bearing of N 32°39′33″ E, a distance of 271.17 feet to a set 5/8 inch rebar; Thence a bearing of N 04°02′23″ E, a distance of 26.33 feet to a set 5/8 inch rebar; Thence a bearing of N 24°01′46″ E, a distance of 173.58 feet to a set 5/8 inch rebar; Thence a bearing of N 17°51′33″ E, a distance of 82.33 feet to a set 5/8 inch rebar; Thence a bearing of N 26°24′36″ E, a distance of 44.80 feet to a set 5/8 inch rebar; Thence a bearing of N 24°14′17" E, a distance of 124.29 feet to a set 5/8 inch rebar; Thence a bearing of N 16°53′15″ E, a distance of 15.92 feet to a set 5/8 inch rebar; Thence a bearing of N 49°48′55″ E, a distance of 11.74 feet to a set 5/8 inch rebar; Thence a bearing of N 70°20′28″ W, a distance of 26.84 feet to a set 5/8 inch rebar; Thence a bearing of N 84°13′28″ W, a distance of 23.56 feet to a set 5/8 inch rebar; Thence a bearing of S 79°27′16″ W, a distance of 30.26 feet to a set 5/8 inch rebar; Thence a bearing of N 20°17′19″ E, a distance of 181.01 feet to a set 5/8 inch rebar; Thence a bearing of N 30°31′52″ E, a distance of 38.70 feet to a set 5/8 inch rebar; Thence a bearing of N 19°13′54″ E, a distance of 27.06 feet to a set 5/8 inch rebar; Thence a bearing of N 34°03′50″ E, a distance of 51.08 feet to a set 5/8 inch rebar; Thence a bearing of S 60°34′24″ E, a distance of 12.85 feet to a set 5/8 inch rebar; Thence a bearing of S 03°51′11″ E, a distance of 14.76 feet to a set 5/8 inch rebar; Thence a bearing of S 33°04′55" W, a distance of 34.86 feet to a set 5/8 inch rebar; Thence a bearing of S $07^{\circ}03'16''$ W, a distance of 22.28 feet to a set 5/8 inch rebar; Thence a bearing of S 03°06′17" E, a distance of 58.51 feet to a set 5/8 inch rebar; Thence a bearing of N 69°50′54″ E, a distance of 13.40 feet to a set 5/8 inch rebar; Thence a bearing of N 39°06′06″ E, a distance of 43.03 feet to a set 5/8 inch rebar; Thence a bearing of N 09°38′16″ E, a distance of 41.26 feet to a set 5/8 inch rebar; Thence a bearing of N 20°13′35″ E, a distance of 37.44 feet to a set 5/8 inch rebar





Annexation Parcel 122.407 Acres continued

Thence a bearing of N 07°20′33″ E, a distance of 127.34 feet to a set 5/8 inch rebar; Thence a bearing of S 80°40′48″ E, a distance of 5.56 feet to a set 5/8 inch rebar; Thence a bearing of S 16°17′15″ E, a distance of 9.29 feet to a set 5/8 inch rebar; Thence a bearing of S 34°48′19″ E, a distance of 8.17 feet to a set 5/8 inch rebar; Thence a bearing of N 68°23′07" E, a distance of 5.18 feet to a set 5/8 inch rebar; Thence a bearing of N 10°06′31″ E, a distance of 14.68 feet to a set 5/8 inch rebar; Thence a bearing of N 13°35′37″ W, a distance of 18.40 feet to a set 5/8 inch rebar; Thence a bearing of N 02°08′37″ E, a distance of 43.68 feet to a set 5/8 inch rebar; Thence a bearing of N 01°48′39″ W, a distance of 139.18 feet to a set 5/8 inch rebar; Thence a bearing of N 03°55′23″ W, a distance of 46.01 feet to a set 5/8 inch rebar; Thence a bearing of N 07°43′49″ E, a distance of 25.14 feet to a set 5/8 inch rebar; Thence a bearing of N 10°58′21″ W, a distance of 18.09 feet to a set 5/8 inch rebar; Thence a bearing of N 02°42′19″ W, a distance of 71.71 feet to a set 5/8 inch rebar; Thence a bearing of N 89°15′39″ E, a distance of 9.15 feet to a set 5/8 inch rebar; Thence a bearing of S 28°34′14″ E, a distance of 39.66 feet to a set 5/8 inch rebar; Thence a bearing of S 84°54′05″ E, a distance of 12.46 feet to a set 5/8 inch rebar; Thence a bearing of S 52°12′49″ E, a distance of 34.50 feet to a set 5/8 inch rebar; Thence a bearing of S 75°29′46″ E, a distance of 24.37 feet to a set 5/8 inch rebar; Thence a bearing of N 84°33′55″ E, a distance of 60.44 feet to a set 5/8 inch rebar; Thence a bearing of N 70°11′14″ E, a distance of 34.88 feet to a set 5/8 inch rebar; Thence a bearing of N 41°07′48″ E, a distance of 9.75 feet to a set 5/8 inch rebar; Thence a bearing of N 78°05′20″ E, a distance of 6.08 feet to a set 5/8 inch rebar; Thence a bearing of S 39°11′54″ E, a distance of 13.19 feet to a set 5/8 inch rebar; Thence a bearing of S 81°04′23″ E, a distance of 14.76 feet to a set 5/8 inch rebar; Thence a bearing of N 67°52′49″ E, a distance of 12.07 feet to a set 5/8 inch rebar; Thence a bearing of N 00°37′45″ E, a distance of 11.29 feet to a set 5/8 inch rebar; Thence a bearing of N 57°57′04″ W, a distance of 31.70 feet to a set 5/8 inch rebar; Thence a bearing of S 79°29′15″ W, a distance of 23.73 feet to a set 5/8 inch rebar; Thence a bearing of S 49°24′59′ W, a distance of 19.65 feet to a set 5/8 inch rebar; Thence a bearing of S 84°42′23″ W, a distance of 74.55 feet to a set 5/8 inch rebar; Thence a bearing of N 53°51′26″ W, a distance of 51.76 feet to a set 5/8 inch rebar; Thence a bearing of N 32°42′31″ W, a distance of 35.06 feet to a set 5/8 inch rebar; Thence a bearing of N 44°38′04″ W, a distance of 49.65 feet to a set 5/8 inch rebar; Thence a bearing of N 17°34′34″ W, a distance of 32.60 feet to a set 5/8 inch rebar; Thence a bearing of N 00°58′27″ E, a distance of 26.29 feet to a set 5/8 inch rebar; Thence a bearing of N 03°40′40″ W, a distance of 95.42 feet to a set 5/8 inch rebar; Thence a bearing of N 26°53′57″ W, a distance of 18.33 feet to a set 5/8 inch rebar;





Annexation Parcel 122.407 Acres continued

Thence a bearing of N $03^{\circ}37'53''$ E, a distance of 115.87 feet to a set 5/8 inch rebar; Thence a bearing of N $06^{\circ}18'13''$ W, a distance of 114.45 feet to a set 5/8 inch rebar; Thence a bearing of N $14^{\circ}06'06''$ W, a distance of 14.15 feet to a set 5/8 inch rebar;

Thence leaving said O.H.W.L a bearing of N 82°00′22″ E, a distance of 561.17 feet to a set 5/8 inch rebar with aluminum cap monument marking the center 1/4 corner of said Section 31;

Thence a bearing of N 86°14′56″ E, a distance of 802.60 feet to a set 5/8 inch rebar;

Thence a bearing of S 83°07′01″ E, a distance of 533.50 feet to a set 5/8 inch rebar marking the northeast corner of the W1/2 of the SE1/4, said Section 31 and the northwest corner of a parcel of land as described by Warranty Deed Inst. No. 230389, deed records of said Valley County;

Thence on the west boundary of said Inst. No. 230389, a bearing of S 00°16′59″ W, a distance of 264.80 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Warranty Deed recorded as Inst. No. 422145 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 422145, a bearing of S 00°14′35″ W, a distance of 264.68 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Affidavit of Surviving Joint Tenant recorded as Inst. No. 392279 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 392279, bearing of S 00°13′04″ W, a distance of 264.76 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Deed of Trust recorded as Inst. No. 161318 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 161318, a bearing of S 00°14′39″ W, a distance of 594.80 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Warranty Deed recorded as Inst. No. 415008 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 415008, a bearing of S 00°15′26″ W, a distance of 293.54 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Warranty Deed Inst. No. 417004 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 417004, a bearing of S 00°13′42″ W, a distance of 293.45 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Special Warranty Deed Inst. No. 218780 said deed records of Valley County;

Thence on the west boundary of said Inst. No. 218780, a bearing of S 00°16′34″ W, a distance of 329.91 feet to a found 1/2 inch rebar marking the northwest corner of a parcel of land as described by Warranty Deed Inst. No. 393897 said deed records of Valley County;



25 Coyote Trail Cascade, ID 83611 P: 208-382-5726 C: 208-634-6896

Annexation Parcel 122.407 Acres Continued

Thence on the west boundary of said Warranty Deed Inst. No. 393897, a bearing of S 00°19′11″ W, a distance of 329.76 feet to a found 1/2 inch rebar marking the southwest corner of said Warranty Deed and the southeast corner of said W1/2 of the SE1/4, Section 31;

Thence a bearing of N 89°43′25″ W, a distance of 1,328.93 feet on the south boundary of said Section 31 to the **POINT OF BEGINNING**.

Said described parcel of land contains 122.407 acres, more-or-less.

